The state of the state of

0015638

multi

21 45 Z 1965 AUG 6

TO RUCSC/SAC OFFUTT AFB OMAHA NEB RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA

RUCVAA/2D RTS BARKSDALE AFB LA

RUEKDA/DIA WASHDC

P Ø62137Z

FM NPIC WASHDC

RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD

RUEPIA/CIA WASHDC

RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF

RUWGAA/2AF BARKSDALE AFB LA

S E C R E T CITE NPIC 5155.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI) 100 PTD

File 08 ADMIN SEC BR P&DS CSD IPD PD PSD PSD-ICB

TID 3

£14.

Office.

Act.

9 Aug 1965

COPIES RECEIVED_

CV No

CAMERA B 7 WAS USED IN MISSION 8035 FLOWN ON 4 AUGUST 1965 PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

- ORIGINAL NEGATIVE: 2.
 - EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: EDGE STATIC IS PRESENT ON THE OUTBOARD EDGE OF THE FILM. MANUFACTURER'S SPLICES ARE LOCATED IN FRAMES 308 AND 1573. A HEAT SPLICE IS LOCATED IN FRAME 1094 AND BETWEEN FRAMES 6/7, 12/13, 29/30, 47/48, 56/57, 63/64, 104/105, 1153/1154, 1930/1931 AND 2009/ 2010.
- C. 9L SIDE: THE IMAGE OF A MANUFACTURER'S SPLICE APPEARS IN MANUFACTURER'S SPLICES ARE LOCATED IN FRAMES 260 AND THERE ARE NUMEROUS EMULSION LIFTS AND GOUGES IN FRAMES 1094 AND 1095. HEAT SPLICES ARE PRESENT IN FRAMES 1095 AND BETWEEN FRAMES 1212/1213. CREASES OCCUR IN FRAME 1211 AND ALONG THE INBOARD EDGE OF FRAMES 1529/1530.
- D. BOTH SIDES: ROLLER CHATTER IS PRESENT ALONG THE INBOARD IRREGULAR PLUS DENSITY STREAKS APPEAR INTERMITTENTLY THROUGH-EDGE. Declassification Review by NGA/DoD

OUT THE MISSION. THE LAST TITLED FRAME OF THE MISSION IS 2216.

- 3. POSITIVE:
- A. PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY CLOUDS OR ATMOSPHERICS.
 - B. PRINTING AND PROCESSING WAS GOOD.
- C. APPROXIMATELY 60 PERCENT OF THE COVERAGE WAS CLOUD COVERED. SECRET

/END OF MESSAGE/